


FIG. 1



2/17

FIG. 2




FIG. 3






FIG. 4




3/17

FIG. 5




4/17

FIG. 6




5/17

FIG. 7




6/17

FIG. 8



7/17

FIG. 9



8/17

FIG. 10





FIG. 11





9/17

FIG. 12





FIG. 13


122A

DEFECT ADDRESS	SPARE ADDRESS	OTHER INFO.
ADDRESS aaaa	ADDRESS gggg	
ADDRESS bbbb	ADDRESS kkkk	
ADDRESS cccc	ADDRESS mmmm	
ADDRESS dddd	ADDRESS nnnn	
⋮	⋮	

10/17

FIG. 14







10/547195

12/17

FIG. 16





14/17




FIG. 18

15/17

FIG. 19






FIG. 20



16/17

FIG. 21





10/547195

17/17

FIG. 22

